

Inspection Photos

Operator: Hilcorp Energy
API: 067-07583
Date: 7/13/2021



Photo 1. View the project area from the northwestern corner facing center.



Photo 2. View of the northern project area from the northwestern corner facing eastward. Revegetation is progressing with western wheatgrass, crested wheatgrass, and rubber rabbitbrush.



Photo 3. View of the western project area from the northwestern corner facing southward.




Photo 4. View of Russian knapweeds within the northwestern working area. Approximately 75 individuals observed.



Photo 5. View the reference area comprised of sagebrush shrubland and pinyon/juniper woodland with understory of squirreltail, greasewood, and threadleaf sunflower.