

**UTAH GAS OP LTD DBA UTAH GAS CORP
DRAGON TRAIL UNIT-62S102W 26SWSE
Location # 314307**



Weeds on location. No battery sign at tank battery.

**UTAH GAS OP LTD DBA UTAH GAS CORP
DRAGON TRAIL UNIT-62S102W 26SWSE
Location # 314307**



No api# on well tag/sign.



Weeds on location.

**UTAH GAS OP LTD DBA UTAH GAS CORP
DRAGON TRAIL UNIT-62S102W 26SWSE
Location # 314307**



Sediment movement in location ditch.



Sediment movement in location ditch.

**UTAH GAS OP LTD DBA UTAH GAS CORP
DRAGON TRAIL UNIT-62S102W 26SWSE
Location # 314307**



Erosion of hillside from storm water flow of location ditch.

**UTAH GAS OP LTD DBA UTAH GAS CORP
DRAGON TRAIL UNIT-62S102W 26SWSE
Location # 314307**



Access to location DTU 1056 and DTU 1001



Erosion of road and movement of sediment.

**UTAH GAS OP LTD DBA UTAH GAS CORP
DRAGON TRAIL UNIT-62S102W 26SWSE
Location # 314307**



Road Access road is not maintained in a stable condition.



Shoulder of road is washing away and exposing gas line. 39.83447 108.80650

**UTAH GAS OP LTD DBA UTAH GAS CORP
DRAGON TRAIL UNIT-62S102W 26SWSE
Location # 314307**



Exposed gas line.



Exposed gas line.

**UTAH GAS OP LTD DBA UTAH GAS CORP
DRAGON TRAIL UNIT-62S102W 26SWSE
Location # 314307**



**Culvert running under road 39.83809, -108.80713.
No inlet or outlet found.**

**UTAH GAS OP LTD DBA UTAH GAS CORP
DRAGON TRAIL UNIT-62S102W 26SWSE
Location # 314307**



**UTAH GAS OP LTD DBA UTAH GAS CORP
DRAGON TRAIL UNIT-62S102W 26SWSE
Location # 314307**



**Erosion rill crossing access road.
Weeds on access road.**

**UTAH GAS OP LTD DBA UTAH GAS CORP
DRAGON TRAIL UNIT-62S102W 26SWSE
Location # 314307**



Wash out from erosion rill crossing access road.

**UTAH GAS OP LTD DBA UTAH GAS CORP
DRAGON TRAIL UNIT-62S102W 26SWSE
Location # 314307**



Erosion of road at the entrance of location.



Access roads and BMPs not maintained in a stable condition.