

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/15/2021

Submitted Date:

07/16/2021

Document Number:

689806018**FIELD INSPECTION FORM**Loc ID 316742 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10691Name of Operator: PHOENIX RESOURCES LLCAddress: 5566 S SYCAMORE STREETCity: LITTLETON State: CO Zip: 80120**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Heffner, Taylor	303-219-3362	theffner@phxresources.com	

**General Comment:**

Inspector on location to perform FLIR inspection in response to venting complaint. Complaint document number 2000449767. Venting observed via FLIR at wellhead, gauge hatch, and pipe on crude oil tank.

**Optical Gas Imaging Survey**Survey Type: ComplaintCurrent Operations: ☒ Production ☐ Workover ☐ Flowback ☐ Referred to APCDGPS(entrance of location): Lat: 40.350448 Long: -107.196315Wind: Calm Speed:        (mph) Direction From: SW Weather: Partly Temperature: 74 (F)Assisting Staff: Emily Waldron Camera #: 3☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
10:32	AM	10:39	AM	Wellhead(s)
				Oil Tank(s)

Comment: Venting observed via FLIR at wellhead, gauge hatch, and pipe on crude tank.

Corrective Action: Immediately cease venting/flaring. Submit Form 4 for review and approval to vent or flare. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: 07/17/2021**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689806019	FLIR Video 1 of 2 - wellhead venting	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5481185">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5481185</a>
689806020	FLIR Video 2 of 2 - tank venting	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5481186">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5481186</a>