

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/11/2021

Submitted Date:

07/16/2021

Document Number:

688800027

## FIELD INSPECTION FORM

 Loc ID 326339 Inspector Name: Hughes, Jim On-Site Inspection  2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 10663Name of Operator: ENDURING RESOURCES LLCAddress: 1050 17TH STREET SUITE 2500City: DENVER State: CO Zip: 80265**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**12 Number of Comments2 Number of Corrective Actions

- 
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Felix, Andrea		afelix@enduringresources.com	All inspections
Walter, Kyle		kwalter@enduringresources.com	All Inspections
Fischer, Alex		alex.fischer@state.co.us	
Heil, John		john.heil@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216258	WELL	PR	11/04/2015	GW	067-07864	WEST ANIMAS-UNIVERSITY 9-2	EI

**General Comment:**

On July 11, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Enduring Resources West Animas University #9-2. For the most recent field inspection report of this facility, please refer to document #693901643.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Free standing sign near location entrance.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Previous operator contact information labeled on PBV.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	09/16/2021
Emergency Contact Number:			
Comment:	Posted on location sign.		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
Lube Oil	Pump Jack	<= 1 bbl	
Comment:	Concrete pad for pump jack is stained with oil. Stained gravel beneath exhaust piping.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.		Date: 08/16/2021
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Guard fencing.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Steel pipe barricade fencing for pipeline riser.		
Corrective Action:		Date:	
<b>Equipment:</b>			
Type: Flow Line	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Natural gas powered.		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		37.220311,-107.864784
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	95 bbl.	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Wells Served By Facilities Above**

**AirsID**

API Number	API Number	AirsID
067-07864		

**Venting:**

Yes/No		
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 216258 Type: WELL API Number: 067-07864 Status: PR Insp. Status: EI

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Pass			
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	

Comment: Secondary containment for chemical injection system and lube oil container. Drip pot on load out line for PBV.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<span style="color: blue;">On July 11, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Enduring Resources West Animas University #9-2. For the most recent field inspection report of this facility, please refer to document #693901643. Concrete pad for pump jack is stained with oil. Stained gravel beneath exhaust piping. The PBV on location lists the previous operator. Comply with Rule 605.h.</span>	hughesjo	07/16/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800029	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5481256">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5481256</a>