

Inspection Photos

Location Name: CAERUS PICEANCE LLC HYRUP-68S96W /2NWSE

Location ID: 334158



Photo #4470 from entrance to location.



Photo #4471 from entrance to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC HYRUP-68S96W /2NWSE

Location ID: 334158



Photo #4472 Multiple places with undesirable plant species.



Photo #4473 Multiple places with undesirable plant species.



Inspection Photos

Location Name: CAERUS PICEANCE LLC HYRUP-68S96W /2NWSE

Location ID: 334158



Photo #4474 Location lacks stabilization.



Photo #4475 No form of tracking BMP located at entrance to location.