

Inspection Photos

Location Name: CAERUS PICEANCE LLC MURRAY-68S96W /1SESW

Location ID: 334086



Photo #4482 from entrance to location.



Photo #4483 Location lacks stabilization.

Inspection Photos

Location Name: CAERUS PICEANCE LLC MURRAY-68S96W /1SESW

Location ID: 334086



Photo #4484 location lacks stabilization.



Photo #4485 No form of tracking BMP located at entrance to location.