

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/12/2021

Submitted Date:

07/13/2021

Document Number:

699803391

FIELD INSPECTION FORM

Loc ID 324328 Inspector Name: De Paolo, Corey On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
19 Number of Comments
3 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 OGCC Operator Number: 10456
 Name of Operator: CAERUS PICEANCE LLC
 Address: 1001 17TH STREET #1600
 City: DENVER State: CO Zip: 80202

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerusoilandgas.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
279199	WELL	PR	11/01/2006	GW	045-11012	PUCKETT 251-1	PR

General Comment:

COGCC Inspection Report Summary
 On Monday 7/12/21 at approximately 14:30 hours, I, Inspector Corey De Paolo, Conducted an on-site inspection at CAERUS PICEANCE LLC PUCKETT-67S97W /1NWNE, Location #324328 in Garfield County Colorado.
 While there, I observed normal production operations.
 During this inspection the following compliance issues were observed:

- 1) Trash on location with a corrective action date of 7/20/21.
- 2) Flow line heating insulation open ended and not capped with a corrective action date of 7/26/21.
- 3) Location lacks stabilization. No form of tracking BMP at entrance to location with a corrective action date of 7/27/21.

- The Location is located in a high priority habitat area. Additionally the location is located in a black bear habitat area.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.
 This is a summary of inspection report.

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Good Housekeeping:

Type	TRASH		
Comment:	Trash on location.		
Corrective Action:	Operators will properly dispose of all trash.	Date:	07/20/2021

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Livestock panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Barbed wire fence		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Barbed wire fence		
Corrective Action:		Date:	

Equipment:

Type: Horizontal Heated Separator	# 1		corrective date
Comment:			
Corrective Action:		Date:	

Type: Other	# 1	
Comment:	Flow line heating insulation open ended and not capped.	
Corrective Action:	Operators will prevent and minimize adverse impacts to wildlife resources.	Date: 07/26/2021
Type: Plunger Lift	# 1	
Comment:	Well on plunger lift	
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:	All meter runs have been calibrated in the last year.	
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment:	No form of pressure monitoring equipment located on braden heads. All braden head valves are accessible.	
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment:		
Corrective Action:		Date:
Type: Deadman # & Marked	# 2	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Centralized containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Centralized containment			
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 279199 Type: WELL API Number: 045-11012 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Fail					No form of tracking BMP at entrance to location
Gravel	Fail					Gravel insufficient
		Compaction				
		Gravel				
Ditches						
Berms						
		Culverts				
Compaction	Fail					Location lacks stabilization
				Material Handling And Spill Prevention		Chemical tank
		Sediment Traps				
		Berms				
		Check Dams				
Sediment Traps						

Comment: Location lacks stabilization. No form of tracking BMP at entrance to location.

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations.

Date: 07/27/2021

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Refer to Housekeeping, Equipment and Storm water for corrective actions.	depaoloc	07/13/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402745721	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5477480
699803392	Photos for Insp. #699803391	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5477474