

# Inspection Photos

API: 071-06339

Operator: OGRIS OPERATING LLC

Inspection Date: 7/7/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-06339 | Date: 7/7/2021

## Inspection Photos



**Photo 1.** Facing northwest along the main access road. Sediment is being deposited onto the road shown at red arrow.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06339 | Date: 7/7/2021



## Inspection Photos



**Photo 2.** There is vehicle disturbance off the side of the road. The disturbance needs to be reclaimed. It appears the culvert was recently excavated at the outlet but may still be filled in with sediment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06339 | Date: 7/7/2021



## Inspection Photos



**Photo 3.** There is vehicle rutting along the main road. Areas of rutting need to be stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06339 | Date: 7/7/2021



## Inspection Photos



**Photo 4.** Facing west toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06339 | Date: 7/7/2021