

# Inspection Photos

API: 071-07414

Operator: OGRIS OPERATING LLC

Inspection Date: 7/7/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-07414 | Date: 7/7/2021

## Inspection Photos



**Photo 1.** There is vehicle rutting and erosion along the road. The white hard hat is placed in the vehicle rut for scale.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07414 | Date: 7/7/2021



## Inspection Photos



**Photo 2.** There is vehicle rutting and erosion along the road. Previous corrective action was not performed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07414 | Date: 7/7/2021



## Inspection Photos



**Photo 3.** Stormwater is not being diverted toward the culvert (red arrow) and is flowing across the road causing erosion.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07414 | Date: 7/7/2021



## Inspection Photos



**Photo 4.** This is the same culvert shown in previous photo which stormwater not properly diverted to the culvert causing erosion.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07414 | Date: 7/7/2021



## Inspection Photos



**Photo 5.** There is vehicle rutting occurring along the road which will only worsen if not repaired. The roads need to be maintained. Previous corrective action was not performed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07414 | Date: 7/7/2021



## Inspection Photos



**Photo 6.** Facing toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07414 | Date: 7/7/2021