

## Inspection Photos

Spill/Release Name: Esperanza 8-6 (4" Off location)

Location ID: 334511 & Spill/Release ID: 480228

Inspection Date: July 1, 2021



**Excavation (right, west side) and the two stockpiles of potentially impacted material (left side, east of the excavation).**



**Excavation containing 4" gathering line and a culvert that runs underneath the road and to the surface water feature located to the west of the excavation.**



## Inspection Photos

Spill/Release Name: Esperanza 8-6 (4" Off location)

Location ID: 334511 & Spill/Release ID: 480228

Inspection Date: July 1, 2021



**View of where the culvert exits the west side of the road and flows through a drainage and into the surface water feature. Note the excavated area within the culvert drainage.**

**Area where the culvert drainage intersects the surface water feature. Note the excavated area within the culvert drainage.**



## Inspection Photos

Spill/Release Name: Esperanza 8-6 (4" Off location)

Location ID: 334511 & Spill/Release ID: 480228

Inspection Date: July 1, 2021



**Close up of where the culvert drainage intersects the surface water feature. Note the excavated area within the culvert drainage.**



**Surface water feature with the excavation in the background (orange fence).**

