

Inspection Photos
Location Name: Elkhorn Company B6
Location ID: 318598



Photo 1 WH sign



Photo 2 WH

Inspection Photos
Location Name: Elkhorn Company B6
Location ID: 318598



Photo 3 Pump Jack



Photo 4 Ancillary Equipment

Inspection Photos
Location Name: Elkhorn Company B6
Location ID: 318598



Photo 5 weeds growing around location ROW and dead man anchors



Photo 6 weeds growing around location ROW and dead man anchors

Inspection Photos
Location Name: Elkhorn Company B6
Location ID: 318598



Photo 7 weeds growing around location ROW and dead man anchors



Photo 8 weeds growing around location ROW and dead man anchors

Inspection Photos
Location Name: Elkhorn Company B6
Location ID: 318598



Photo 9 TB sign



Photo 10 TB

Inspection Photos
Location Name: Elkhorn Company B6
Location ID: 318598



Photo 11 Stained soil by valve



Photo 12 Stained soil by valve

Inspection Photos
Location Name: Elkhorn Company B6
Location ID: 318598



Photo 13 Stained soil by valve



Photo 14 Stained soil by valve

Inspection Photos
Location Name: Elkhorn Company B6
Location ID: 318598



Photo 15 Gas Meter Run



Photo 16 Flow line manifold

Inspection Photos
Location Name: Elkhorn Company B6
Location ID: 318598



Photo 17 Stained soil by the Flow line manifold



Photo 18 Stained soil by the Flow line manifold

Inspection Photos
Location Name: Elkhorn Company B6
Location ID: 318598



Photo 19 Stained soil by the Flow line manifold



Photo 20 Horizontal Heated Separator

Inspection Photos
Location Name: Elkhorn Company B6
Location ID: 318598



Photo 21 ECD