

# Inspection Photos

API: 017-07727

Operator: HIGH PLAINS ENERGY LLC

Inspection Date: 7/12/2021



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07727 | Date: 7/12/2021

## Inspection Photos



**Photo 1.** Facing north along the access road toward the location. Location sign is posted next to access road but is covered with weed growth.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07727 | Date: 7/12/2021

## Inspection Photos



**Photo 2.** Facing northeast at the location. Wellhead is at center of location shown at red arrow.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07727 | Date: 7/12/2021

## Inspection Photos



**Photo 3.** Facing east toward the location. There are unused pipe risers shown at red arrow.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07727 | Date: 7/12/2021

## Inspection Photos



**Photo 4.** Facing east along the stockpiled soil. The stockpiled soil has not been replaced and recontoured. There are undesirable weeds (Kochia sp.) throughout the stockpiled soil . The shovel (4.5 ft.) indicates growth of weeds along the soil piles.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07727 | Date: 7/12/2021

## Inspection Photos



**Photo 5.** There is tank berms that remains and unused fence posts. There is oily waste shown at red arrow.



**Photo 6.** There is oily waste observed inside the berm area shown in previous photo.



## Inspection Photos



**Photo 7.** There is various unused equipment and debris laying on the ground. There is a berm that remains in this area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07727 | Date: 7/12/2021

## Inspection Photos



**Photo 8.** Facing southeast toward the location. There are multiple berm areas, unused equipment, debris, electrical equipment, and storage shed in disrepair.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07727 | Date: 7/12/2021

## Inspection Photos



**Photo 9.** There is a shed in disrepair at the southeast side of the location. Various unused equipment remains near the shed.



**Photo 10.** View of inside the shed. There is various piping risers, and supplies inside the shed.



## Inspection Photos



**Photo 11.** There are oil stained soils inside the shed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07727 | Date: 7/12/2021

## Inspection Photos



**Photo 12.** Facing southwest along the soil pile which is cover with undesirable weeds (Kochia). There is also a pile liner debris and oil stained soil shown at red arrow.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07727 | Date: 7/12/2021

## Inspection Photos



**Photo 13.** Facing northeast toward the east side of the pad. There are undesirable weeds (*Kochia* sp.) throughout the stockpiled soil.



## Inspection Photos



**Photo 14.** Facing toward the wellhead at the center of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07727 | Date: 7/12/2021

## Inspection Photos



**Photo 15.** There is electrical wires extending out of the ground near the wellhead.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07727 | Date: 7/12/2021

## Inspection Photos



**Photo 16.** Facing toward west side of the location. There is electrical wiring extending out of the ground in this area. There is a cellar with exposed electrical wiring inside.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07727 | Date: 7/12/2021

## Inspection Photos



**Photo 17.** Facing southeast toward the location Interim reclamation has not been performed. Unused areas of the location have not been reclaimed.



## Inspection Photos



**Photo 18.** Northeast corner of the location facing southwest. Unused areas of the location have not been reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07727 | Date: 7/12/2021