

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/19/2021

Submitted Date:

07/21/2021

Document Number:

689806021**FIELD INSPECTION FORM**Loc ID 316764 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 6720Name of Operator: ROBERT L BAYLESS PRODUCER LLCAddress: 621 17TH ST STE 2300City: DENVER State: CO Zip: 80293**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Trujillo, Helen		notices@rlbayless.com	<a href="#">All inspections</a>
Kellerby, Shaun		shaun.kellerby@state.co.us	
thomas, john	505-326-2659	jthomas@rlbayless.com	

**General Comment:**

Inspector on location in response to venting complaint. Complaint document number 200449782. FLIR inspection performed in response to complaint. Venting observed at vent tank, vertical separator, and wellhead.

**Optical Gas Imaging Survey**Survey Type: ComplaintCurrent Operations: ☒ Production ☐ Workover ☐ Flowback ☐ Referred to APCDGPS(entrance of location): Lat: 40.395400 Long: -107.221837Wind: Calm Speed:        (mph) Direction From: S Weather: Clear Temperature:        (F)Assisting Staff: Emily Waldron Camera #: 3☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM
11:00	AM	11:10	AM

Equipment
Wellhead(s)
Other
Separation Equipment

Comment: FLIR video documented venting at vent tank, wellhead, and vertical separator. Inspector spoke with John Thomas of Bayless on 7/21 and was informed that pumper would be sent out to address leaks at wellhead and separator and that operator was in communication with CDPHE regarding how to manage casing gas on location.

Corrective Action: Immediately cease venting/flaring. Submit Form 4 for review and approval to vent or flare.

Date: 07/22/2021**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689806022	FLIR - wellhead venting	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5485032">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5485032</a>
689806023	FLIR - separator venting	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5485033">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5485033</a>
689806024	FLIR - vent tank venting	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5485034">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5485034</a>