


Inspection Photos
Location Name: Stroh O 13-21D
API #123-30040



Wellhead



Variance tag