

Inspection Photos
Location Name: Our Diane 31-27
Location ID: 328043




Photo 1 WH sign

Photo 2 WH

Inspection Photos
Location Name: Our Diane 31-27
Location ID: 328043



Photo 3 Stained soil near WH

Photo 4 Stained soil around WH

Inspection Photos
Location Name: Our Diane 31-27
Location ID: 328043



Photo 5 Stained soil near WH at Pump Jack base

Photo 6 Pump Jack

Inspection Photos
Location Name: Our Diane 31-27
Location ID: 328043



Photo 7 electric panel, fiber optic box

Photo 8 TB sign

Inspection Photos
Location Name: Our Diane 31-27
Location ID: 328043



Photo 9 TB

Photo 10 stained soil by valve on south side of crude tank

Inspection Photos
Location Name: Our Diane 31-27
Location ID: 328043



Photo 11 Horizontal Heated Separator

Photo 12 ECD

Inspection Photos
Location Name: Our Diane 31-27
Location ID: 328043




Photo 13 Gas Meter Run

Photo 14 Card in meter house indicates that calibration is not current

Inspection Photos
Location Name: Our Diane 31-27
Location ID: 328043



Photo 15 Gas Meter Run

Photo 16 Chart in meter box is current from 7-16-2021

Inspection Photos
Location Name: Our Diane 31-27
Location ID: 328043



Photo 17 Stained soil around a Locked Cellar