

Inspection Photos
Location Name: Pace Connelly 3
Location ID: 318508



Photo 1 WH sign

Photo 2 Stained soil around WH

Inspection Photos
Location Name: Pace Connelly 3
Location ID: 318508



Photo 3 Stained soil to the east of the WH

Photo 4 Pump Jack

Inspection Photos
Location Name: Pace Connelly 3
Location ID: 318508



Photo 5 Stained soil at the base of the pump jack

Photo 6 Ancillary equipment

Inspection Photos
Location Name: Pace Connelly 3
Location ID: 318508



Photo 7 TB sign

Photo 8 TB

Inspection Photos
Location Name: Pace Connelly 3
Location ID: 318508



Photo 9 Stained soil on the SE side of the crude oil tank

Photo 10 Horizontal Heated Separator

Inspection Photos
Location Name: Pace Connelly 3
Location ID: 318508



**Photo 11 Stained soil by the flow line riser at the Horiz.
Heated Sep.**

Photo 12 ECDs