



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PUMP JACK		
Comment:	fabricated square tubing		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Chainlink topped with barb wire		
Corrective Action:		Date:	

**Equipment:**

Type	Quantity	Comment	Corrective Action	Date	corrective date
Prime Mover	# 1	electric motor			
Pump Jack	# 1				
Bradenhead	# 1	appears to be plumbed to surface			
Ancillary equipment	# 1	electric panel			

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 248291 Type: WELL API Number: 123-16089 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 09/24/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: appears to be plumbed to surface

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On Wednesday 7/21/2021 at approximately 1335 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location:                      Wyatt 33-22 at API #05-123-16089                      in Weld County Colorado.                      While there, I observed a wellsite, PR at the time of inspection.                      During this inspection no compliance issues were observed:                      See attached photos.                      Location: dry, Weather: cloudy.                      No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	revasr	07/21/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699304126	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5485721">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5485721</a>