

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/13/2021

Submitted Date:

07/15/2021

Document Number:

701101731

FIELD INSPECTION FORMLoc ID 314307 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10539

Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP

Address: 1125 ESCALANTE DR

City: RANGELY State: CO Zip: 81648

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

12 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Murray, Richard		g.richard.murray@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Gas, UtahGasCorp	970-693-6021	inspections@utahgascorp.com	Inspection mail box
Thompson, Bud		BLThomps@BLM.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228287	WELL	PR	06/01/2002	GW	103-05113	DRAGON TRAIL UNIT 1001	PR

General Comment:**COGCC Routine Inspection Report Summary**

This location is in close proximity of water drainage that runs to Douglas Creek and in a Sensitive Wildlife Habitat (SWH) Details (Mule Deer) Parks & Wildlife (CPW) (Black Bear)

During this inspection the following compliance issues were observed:

- No battery sign at tank battery.
- Weeds on location and access road.
- Access road is not maintained in a stable condition.
- Insufficient cover over flowline. Shoulder of road is washing away and exposing gas line(39.83447 108.80650)
- Storm water BMPs on location and access road are not maintained.

Sediment movement in location ditch. Erosion of hillside from storm water flow of location ditch.

Sediment moving on and across access road. Road has erosion rill running across it and has created erosion into water drainage that runs to Douglas Creek. Shoulder of road is washing away and exposing gas line(39.83447 108.80650). Culvert running under road (39.83809, -108.80713) No inlet or outlet found.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location

Lease Road:			
Type	Access		
comment:	Access road is not maintained in a stable condition.		
Corrective Action	Comply 603.l.	Date:	07/31/2021

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	No api# on well tag/sign.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	No battery sign at tank battery.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	10/16/2021

Emergency Contact Number:

Comment:	911	
Corrective Action:		Date: _____

Good Housekeeping:		
Type	WEEDS	
Comment:	Weeds on location and access road.	
Corrective Action:	Comply with Rule 606	Date: 07/31/2021

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	Bradenhead is accessible.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	<50 BBLS	Open Top		,

Comment:		
Corrective Action:		Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	30 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 228287 Type: WELL API Number: 103-05113 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well

Corrective Action:

Date:

Flowline

#1 Type: Sales Line

of Lines

Flowline DescriptionFlowline Type: Sales LineSize: 4"Material: Carbon Steel

Variance:

Age:

Contents: Natural GasIntegrity Summary

Failures:

Spills:

Repairs Made:

Coatings:

H2S:

Cathodic Protection:

Pressure Testing

Witnessed:

Test Result:

Charted:

COGCC Rules(check all that apply)☐ 1101. Installation and Reclamation☒ 1102. Operations, Maintenance, and Repair☐ 1103. AbandonmentComment: Insufficient cover over flowline.Shoulder of road is washing away and exposing gas line(39.83447 108.80650)

Corrective Action:

Cover flowline sufficient to protect from damage to comply with rule 1102.e.Date: 08/16/2021

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						
Ditches	Fail					
Seeding						
		Ditches	Fail			
		Culverts	Fail			39.83809, -108.80713
		Compaction	Fail			

Comment: Sediment movement in location ditch. Erosion of hillside from storm water flow of location ditch.
Sediment moving on and across access road. Road has erosion rill running across it and has created erosion into water drainage that runs to Douglas Creek. Shoulder of road is washing away and exposing gas line(39.83447 108.80650). Culvert running under road (39.83809, -108.80713) No inlet or outlet found.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 07/31/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402748980	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5479888
701101740	Inspection 701101731 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5479884