

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHORE-67S95W /16SWNE

Location ID: 334599



Photo #4504 from entrance to location.



Photo #4505 from entrance to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHORE-67S95W /16SWNE

Location ID: 334599



Photo #4506 from entrance to location.



Photo #4507 Multiple places with undesirable plant species on location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHORE-67S95W /16SWNE

Location ID: 334599



Photo #4508 Multiple places with undesirable plant species on location.



Photo #4509 location lacks stabilization.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHORE-67S95W /16SWNE

Location ID: 334599



Photo #4510 location lacks stabilization.



Photo #4511 no form of tracking BMP located at the entrance to location.