

## Inspection Photos

Location Name: CAERUS PICEANCE LLC GARDNER-67S95W /16NWSW

Location ID: 335025



**Photo #4512 from entrance to location.**



**Photo #4513 No battery sign located at the tank battery.**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC GARDNER-67S95W /16NWSW

Location ID: 335025



Photo #4514 from entrance to location.



Photo #4515 Flow line heating insulation open ended and not capped.

## Inspection Photos

Location Name: CAERUS PICEANCE LLC GARDNER-67S95W /16NWSW

Location ID: 335025



**Photo #4516 Stained soils outside of containment.**