

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/20/2021

Submitted Date:

07/20/2021

Document Number:

699803427

FIELD INSPECTION FORM

Loc ID 335041 Inspector Name: De Paolo, Corey On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

18 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerusoilandgas.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295092	WELL	PR	08/01/2020	GW	045-15645	FEDERAL HAGEN 15-13BB (PI-16)	PR
295101	WELL	PR	10/11/2008	GW	045-15647	FEDERAL 16-9 (PI-16)	PR
295102	WELL	PR	10/24/2008	GW	045-15648	FEDERAL 16-9BB (PI-16)	PR
295103	WELL	PR	11/01/2019	GW	045-15650	FEDERAL 16-16BB (PI-16)	PR
295104	WELL	PR	10/26/2008	GW	045-15651	FEDERAL 16-16 (PI-16)	PR
295105	WELL	PR	10/24/2008	GW	045-15652	FEDERAL 15-12BB (PI-16)	PR
295106	WELL	SI	04/01/2020	GW	045-15653	FEDERAL 15-12 (PI-16)	SI

General Comment:

[COGCC Inspection Report Summary](#)
On Tuesday 7/20/21 at approximately 12:30 hours, I, Inspector Corey De Paolo, Conducted a follow up at CAERUS PICEANCE LLC FEDERAL HAGEN-67S95W /16NESE, Location #335041 in Garfield County Colorado.
Refer to document #699802699 inspection conducted on 3/2/21. All previous corrective actions have been completed.
While there, I observed normal production operations.
This is a summary of inspection report.

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	LOCATION		
Comment:	Barbed wire fence around location		
Corrective Action:		Date:	

Equipment:

Type			corrective date
Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Plunger Lift	# 7		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Vertical Heated Separator	# 7		
Comment:			
Corrective Action:		Date:	
Gas Meter Run	# 1		
Comment:	Summit midstream		
Corrective Action:		Date:	
Gas Meter Run	# 7		

Comment:	All meter runs have been calibrated in the last year.		Date:	
Corrective Action:			Date:	
Type: Bradenhead	# 7			
Comment:	Pressure transducers located on braden head. All braden head valves are accessible.		Date:	
Corrective Action:			Date:	
Type: Bird Protectors	# 2			
Comment:			Date:	
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		
Comment:					Date:
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Centralized containment			Date:
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	300 BBLs	STEEL AST		
Comment:					Date:
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Centralized containment			Date:
Corrective Action:				Date:

Venting:

Yes/No	NO	
--------	----	--

Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Sediment Traps						
		Berms				
		Culverts				
Gravel						
Ditches						
Berms						
Compaction						
		Sediment Traps				
		Compaction				
Gravel						
		Ditches				
		Gravel				

Comment: Location appears to have been bladed and has some gravel throughout with light compaction. Places with light to no gravel are present on location. Light gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Refer to storm water for corrective actions	depaoloc	07/20/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699803428	Photos for Insp. #699803427	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5485988