

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/07/2021

Submitted Date:

07/22/2021

Document Number:

689806012**FIELD INSPECTION FORM**Loc ID 312952 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10407Name of Operator: ANTLER ENERGY LLCAddress: PO BOX 104City: BAGGS State: WY Zip: 82321**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Evans, Clay		antlerenergy@yahoo.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222992	WELL	PR	07/01/2016	GW	081-06354	PTASYNSKI 3	SI

General Comment:

Routine FIU inspection. Compliance issues observed:
 no bradenhead access apparent
 wellhead sign faded
 production reporting

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Wellhead sign faded and illegible.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	09/22/2021

Emergency Contact Number:			
Comment:	Emergency number not legible on faded wellhead sign.		
Corrective Action:	Install sign to comply with Rule 605.		Date: 08/23/2021

Overall Good: ☐

Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:			
Type	PIT		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	#		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	#		
Comment:	Bradenhead inaccessible or not visible.		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2)		Date: 08/02/2021
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No			

Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 222992 Type: WELL API Number: 081-06354 Status: PR Insp. Status: SI**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: Production report numbers are identical for the last 17 months.Corrective Action: Submit required Form 7(s) to COGCC per rule 413.Date: 08/23/2021

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No stormwater BMPs observed. No apparent soil migration; erosion or soil movement.

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Type: _____ Lined: _____ Pit ID: 100412 Lat: 40.918559 Long: -108.336778

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective

Date:

Fencing:

Fencing Type: Livestock

Fencing Condition: Adequate

Comment:

Corrective

Date:

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective

Date:

Anchor Trench Present:

Oil Accumulation: NO

2+ feet Freeboard:

Comment:

Corrective

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689806025	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5486227