

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401422843

Date Received:
10/09/2017

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100264

Name of Operator: XTO ENERGY INC

Address: 110 W 7TH STREET

City: FORT WORTH State: TX Zip: 76102

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Leonard, Mike

mike.leonard@state.co.us

Fitzgerald, Edie

719-845-2108/719-859-1394

ediefitzgerald@tcenergy.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 687900421

Inspection Date: 09/21/2017

FIR Submit Date: 09/26/2017

FIR Status: _____

Inspected Operator Information:

Company Name: XTO ENERGY INC

Company Number: 100264

Address: PO BOX 6501

City: ENGLEWOOD State: CO Zip: 80155

LOCATION - Location ID: 308915

Location Name: HILL RANCH-634S67W Number: 35SWNW County: LAS ANIMAS

Qtrqr: SWN Sec: 35 Twp: 34S Range: 67W Meridian: 6
W

Latitude: 37.042233 Longitude: -104.862128

FACILITY - API Number: 05-071- -00 Facility ID: 284810

Facility Name: HILL RANCH Number: 35-5

Qtrqr: SWN Sec: 35 Twp: 34S Range: 67W Meridian: 6
W

Latitude: 37.042233 Longitude: -104.862128

CORRECTIVE ACTIONS:

1 ☒ CA# 102974

Corrective Action: Access road needs to be fixed.

Date: 10/26/2017

Response: CA COMPLETED

Date of Completion: 10/06/2017

Operator
Comment:

The access roadway surface was crowned to establish sheet flow to address the tire ruts/erosion issues.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 102975

Corrective Action: Need to address ruts and erosion.

Date: 10/26/2017

Response: CA COMPLETED

Date of Completion: 10/06/2017

Operator
Comment: Stormwater was flowing down the main lease road west of HR 35-05 well pad. This was concentrated flow causing erosion where the tire ruts were. The main lease road was re-graded and surface crowned to create sheet flow. The bar ditch was dominated to receive run off from the main access road. A water bar was installed in the flow line west of the well pad entrance, to reduce the volume of run off to the well pad access road.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: The main lease roadway surface and well pad access road improvements are complete. The tire ruts and erosion issues have been addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: _____

Title: Sr Environmental Tech

Date: 10/9/2017 9:14:15 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401422843	FIR RESOLUTION SUBMITTED
401422852	Roadway improvements

Total Attach: 2 Files