

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/22/2021

Submitted Date:

07/22/2021

Document Number:

700703027

FIELD INSPECTION FORM

 Loc ID _____ Inspector Name: _____ On-Site Inspection
 315513 _____ Ramsey, Scott _____ 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: _____ 96850 _____
 Name of Operator: TEP ROCKY MOUNTAIN LLC _____
 Address: PO BOX 370 _____
 City: _____ PARACHUTE _____ State: _____ CO _____ Zip: _____ 81635 _____
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 10 _____ Number of Comments
 4 _____ Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	
Thomson, Bud		BLThomps@BLM.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230962	WELL	PR	05/18/2015	GW	103-08631	GOVERNMENT (FEDERAL) 298-13-1	PR

General Comment:

COGCC Inspection Report Summary

On Wednesday 7/21/2021 at approximately 1000, I, Inspector Scott Ramsey, conducted a routine inspection at TEP Government 298-13-1, at Location # 315513 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad, there is no evidence of a tracking pad at time of inspection.

During this inspection the following compliance issues were observed:

1. No battery signage
2. Dehy heater is open for wildlife
3. Entrance shows signs of erosion
4. Load out buckets are not plugged

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:	see stormwater		
Corrective Action			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:	No battery signage		
Corrective Action:	Comply with rule 605.e		Date: 10/22/2021
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	Load out buckets are not plugged		
Corrective Action:	install plugs on load out lines		Date: 08/27/2021
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Bradenhead	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:

Type: Ancillary equipment	# 1		
Comment:	chemical tank in olastic containment		
Corrective Action:			Date:
Type: Dehydrator	# 1		
Comment:	Dehy heater is open for wildlife		
Corrective Action:	eliminate wildlife access		Date: 08/27/2021
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	HEATED STEEL AST		,
Comment:	210 bbl tank				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 230962 Type: WELL API Number: 103-08631 Status: PR Insp. Status: PR

Producing Well

Comment: producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
		Berms				

Comment: [1. Entrance shows signs of erosion \(erosion channels present\)](#)

Corrective Action: [Install or repair required BMPs](#)

Date: 08/27/2021

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700703032	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5486466