

**Inspection Photos**  
**Location Name: W. Animas Wheeler #8-1**  
**API: 05-067-07841**



**W. Animas Wheeler #8-1 produced water PBV.**



**W. Animas Wheeler #8-1 production equipment.**



**Inspection Photos**  
**Location Name: W. Animas Wheeler #8-1**  
**API: 05-067-07841**



**Erosion along eastern edge of location.**



**Erosional channel along eastern edge of location.**



**Inspection Photos**  
**Location Name: W. Animas Wheeler #8-1**  
**API: 05-067-07841**



**Staining near generator.**



**Wattles along eastern edge require maintenance.**