

Inspection Photos
Operator: Enduring
API: 067-08489
Date: 7/20/2021



Photo 1. View the project area from the well pad entrance facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing with crested wheatgrass, intermediate wheatgrass, and crested wheatgrass.



Photo 3. View of the eastern project area from the northeastern corner facing southward. Approximately 300 treated musk thistles observed.



Photo 4. View of erosional tunnel in the northern project area approximately 3 feet wide (depth unknown).



Photo 5. View the reference area comprised of gambel oak shrubland with pinyon and juniper trees and scattered ponderosa pine trees. Vegetation in the understory includes western wheatgrass, Indian ricegrass, Indian paintbrush, and goldenweed.