

Inspection Photos
Operator: Benson Montin Greer
API: 067-06135
Date: 7/20/2021



Photo 1. View the project area from the well pad entrance facing center.



Photo 2. View of weed debris within the project area, needs to be removed.



Photo 3. View of the northern fill slope from the northwestern corner facing eastward. Revegetation is progressing with smooth brome, Indian ricegrass, and rubber rabbitbrush.



Photo 4. View of erosional channeling (approx. 12 inches wide and 4-6 inches deep) near the well pad entrance needing stabilization.



Photo 6. View the reference area comprised of gambel oak shrubland with pinyon and juniper trees and scattered ponderosa pine trees. Vegetation in the understory includes western wheatgrass, Indian ricegrass, Indian paintbrush, and goldenweed.