

Inspection Photos
Operator: Enduring
API: 067-08483
Date: 7/20/2021



Photo 1. View the project area from the northwestern corner facing center.



Photo 2. View of the northern project area from the northwestern corner facing eastward. Revegetation is progressing with smooth brome, crested wheatgrass, and western wheatgrass.




Photo 3. View of flowering musk thistles within the northern project area. Approximately 150 individuals observed.



Photo 4. View of erosional channeling (approx. 12 inches wide and 4-6 inches deep) near the well pad entrance needing stabilization.



Photo 5. View the reference area comprised of gambel oak shrubland with pinyon and juniper trees and scattered ponderosa pine trees. Vegetation in the understory includes western wheatgrass, Indian ricegrass, Indian paintbrush, and goldenweed.