

Inspection Photos

Operator: Enduring Resources
API: 067-07915
Date: 7/20/2021



Photo 1. View of the southeastern fill slope facing northeastward. Revegetation is progressing with western wheatgrass, crested wheatgrass, and rubber rabbitbrush.



Photo 2. View of the southwestern project area from the southern corner facing northwestward.



Photo 3. View of erosional rilling and channeling occurring along the access road. Straw bales are not functioning and are not an adequate BMP in this area. Inset shows erosional channeling from eroded berm on fill slope.



Photo 5. View the reference area comprised of pinyon and juniper woodland with scattered ponderosa pine trees and rubber rabbitbrush, western wheatgrass, Indian ricegrass, and sagebrush in the understory.