

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/15/2021

Submitted Date:

07/16/2021

Document Number:

689806015**FIELD INSPECTION FORM**Loc ID 316739 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 52530Name of Operator: MAGPIE OPERATING INCAddress: 2707 SOUTH COUNTY RD 11City: LOVELAND State: CO Zip: 80537**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------|----------------|----------------------------|---------|
| Kellerby, Shaun | | shaun.kellerby@state.co.us | |
| warner, ryan | (970) 669-6308 | magpieoil@yahoo.com | |

General Comment:

Inspector on location to perform FLIR inspection in response to complaint of produced water tank venting. Complaint document number 200449786.

Inspector attempted to perform a routine FIU inspection on 5/24/2021 document number 689805851. Gate was locked during that inspection. Inspector requested gate code in inspection and has not received the code. Inspector was able to walk through gate to document venting during this inspection. Complainant likely trespassed to get visual on tank as thick vegetation prevents visibility of tank from road.

Optical Gas Imaging SurveySurvey Type: ComplaintCurrent Operations: ☒ Production ☐ Workover ☐ Flowback ☐ Referred to APCDGPS(entrance of location): Lat: 40.389254 Long: 107.217900Wind: Calm Speed: (mph) Direction From: SW Weather: Partly Temperature: 73 (F)Assisting Staff Emily Waldron Camera #: 3☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

| Time Survey Start | AM/PM | Time Survey End | AM/PM | Equipment |
|-------------------|-------|-----------------|-------|---------------|
| 10:09 | AM | 10:14 | AM | Water Tank(s) |

Comment: Venting observed via FLIR from gauge hatch and pipe on produced water tank.Corrective Action: Immediately cease venting/flaring. Submit Form 4 for review and approval to vent or flare. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.Date: 07/17/2021**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 402750576 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5481197 |
| 689806016 | FLIR Video 1 of 2 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5481183 |
| 689806017 | FLIR Video 2 of 2 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5481184 |