

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/15/2021

Submitted Date:

07/16/2021

Document Number:

689806018**FIELD INSPECTION FORM**Loc ID 316742 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10691Name of Operator: PHOENIX RESOURCES LLCAddress: 5566 S SYCAMORE STREETCity: LITTLETON State: CO Zip: 80120**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Heffner, Taylor	303-219-3362	theffner@phxresources.com	

General Comment:

Inspector on location to perform FLIR inspection in response to venting complaint. Complaint document number 2000449767. Venting observed via FLIR at wellhead, gauge hatch, and pipe on crude oil tank.

Optical Gas Imaging SurveySurvey Type: ComplaintCurrent Operations: ☒ Production ☐ Workover ☐ Flowback ☐ Referred to APCDGPS(entrance of location): Lat: 40.350448 Long: -107.196315Wind: Calm Speed: (mph) Direction From: SW Weather: Partly Temperature: 74 (F)Assisting Staff: Emily Waldron Camera #: 3☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
10:32	AM	10:39	AM	Wellhead(s)
				Oil Tank(s)

Comment: Venting observed via FLIR at wellhead, gauge hatch, and pipe on crude tank.

Corrective Action: Immediately cease venting/flaring. Submit Form 4 for review and approval to vent or flare. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: 07/17/2021**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402750577	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5481198
689806019	FLIR Video 1 of 2 - wellhead venting	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5481185
689806020	FLIR Video 2 of 2 - tank venting	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5481186