

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/22/2021

Submitted Date:

07/22/2021

Document Number:

699503024**FIELD INSPECTION FORM**Loc ID 320103 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10711Name of Operator: PAINTED PEGASUS PETROLEUM LLCAddress: 16820 BARKER SPRINGS RD #521City: HOUSTON State: TX Zip: 77084**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
		jh@p3petro.com	
Gomez, Jason		jason.gomez@state.co.us	
		jm@p3petro.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202641	WELL	SI	08/01/2020	OW	001-08046	ELAINE 41-18	SI

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Placard needs to be replaced. see pic		
Corrective Action:	Sign not posted or information inaccurate at oil and gas location	Date:	08/22/2021

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

Good Housekeeping:

Type	OTHER		
Comment:	stained soil by load line on oil tank and separator, insulation needs to be cleaned up in separator house, unused automation equipment needs to be removed, weeds need to be managed see pics		
Corrective Action:	Comply with COGCC housekeeping rules	Date:	08/22/2021

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

				corrective date
Type: Ancillary equipment	# 1			
Comment:	automation			
Corrective Action:		Date:		
Type: Plunger Lift	# 1			
Comment:				
Corrective Action:		Date:		
Type: Bradenhead	# 1			
Comment:				
Corrective Action:		Date:		
Type: Deadman # & Marked	# 4			
Comment:				
Corrective Action:		Date:		
Type: Bird Protectors	# 2			
Comment:				
Corrective Action:		Date:		
Type: Vertical Heated Separator	# 2			
Comment:				
Corrective Action:		Date:		

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:				
Corrective Action:		Date:		

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLs	BV CONCRETE		,	
Comment:						
Corrective Action:		Date:				

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:		shares containment with oil tank		
Corrective Action:		Date:		

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 202641 Type: WELL API Number: 001-08046 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 04/28/2020

Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0

Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On 7/22/21 at approximately 1000 I, Inspector Justin Medina conducted an on-site inspection at:</p> <p>Well Name- Elaine 41-18</p> <p>Company Name- P3</p> <p>API- 05-001-08046</p> <p>In Adams County Colorado.</p> <p>While there, I observed SI well</p> <p>Placard needs to be replaced. See pics</p> <p>Sign not posted or information inaccurate at oil and gas location 8/22/21</p> <p>stained soil by load line on oil tank and separator, insulation needs to be cleaned up in separator house, unused automation equipment needs to be removed, weeds need to be managed see pics</p> <p>Comply with COGCC housekeeping rules 8/22/21</p> <p>At time of inspection COGCC data shows production from 7/1/20, however this well uses plunger lift equipment. The COGCC may need to investigate how oil production was shown with plunger lift equipment with no gas production, or flaring reported.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	medinaj	07/22/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699503025	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5487080