

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/15/2021

Submitted Date:

07/23/2021

Document Number:

700300214**FIELD INSPECTION FORM**Loc ID 417859 Inspector Name: LABOWSKIE, STEVE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10417Name of Operator: INCREMENTAL OIL & GAS (FLORENCE) LLCAddress: 113 N SANTA FE AVECity: FLORENCE State: CO Zip: 81226**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Goss, Aaron	303-495-0327	agoss@fremontpetroleum.com	<a href="#">All Inspections</a>
Hart, Tim		thart@fremontpetroleum.com	
Beardslee, Tom		tom.beardslee@state.co.us	
Harkins, Liz		lharkins@fremontpetroleum.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
417858	WELL	PR	06/01/2020	OW	043-06194	Woolly Bugger 34-20	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:	label faded and deteriorated on chemical tank, difficult to read with tank placement near pump jack and labeling facing inward		
Corrective Action:	Install/repair container labels per Rule 605	Date:	08/23/2021
Type	WELLHEAD		
Comment:	View of sign obscured by chemical tank, moving chem tank or sign will improve visibility		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	impacted material/stained soil around wellhead from leaks and/or excessive rod oil use		
Corrective Action:	clean up per Rule 1002.f2(c)	Date:	07/30/2021
Type	DEBRIS		
Comment:	dead and dry vegetation (treated weeds) are combustible		
Corrective Action:	remove debris/combustible material within 25' of equipment per Rule 606 and 610.k	Date:	07/30/2021

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	#		
Comment:	Chemical injection system with adequate spill prevention		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 0		
Comment:			
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2)	Date:	08/23/2021
Type: Prime Mover	# 1		

Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	wellhead		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:	Did not appear to venting to centralized combustor. Gas reporting for gas produced/gas flared stopped 3/1/2020. Form 4 to vent/flare 10/2019 in process. Note new venting sundry notices requirefd by 1/15/2022		
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	417858	Type:	WELL	API Number:	043-06194	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	
Compaction	Pass					

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

**Optical Gas Imaging Survey**Survey Type: RoutineCurrent Operations: ☒ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: \_\_\_\_\_ Long: \_\_\_\_\_

Wind: Calm Speed: 0-2 (mph) Direction From: E Weather: Clear Temperature: (F)

Assisting Staff: \_\_\_\_\_ Camera #: \_\_\_\_\_

☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM
-------------------	-------	-----------------	-------

Equipment
-----------

Flowline
----------

Other
-------

Wellhead(s)
-------------

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700300241	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5487221">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5487221</a>