

# Inspection Photos

Operator: Hilcorp Energy  
API: 067-06524  
Date: 7/20/2021



Photo 1. View of the project area from the northeastern corner facing center.





Photo 2. View of the eastern project area from the northeastern corner facing southward.





Photo 3. View of stained soils (approx. 2ft diam) near the well head.





Photo 4. View the reference area comprised of pinyon and juniper woodland with black sage, snakeweed, Indian ricegrass, and James galleta.