

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/19/2021

Submitted Date:

07/19/2021

Document Number:

699304094**FIELD INSPECTION FORM**Loc ID 318513 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**13 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rwatzman@kpk.com	<a href="#">All Inspections</a>
,		cogcc@kpk.com	<a href="#">All Inspections</a>
,		dnr_cogccenforcement@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241442	WELL	PR	11/01/2019	GW	123-09231	O'HARA 2-9	SI

**General Comment:**

### Location

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	beginning to fade will need replaced in the near future		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	barb wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	hog fence		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	gas engine		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		

Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Berm around tank is flat, needs to be addressed.			
Corrective Action:	Comply with Rule 605.a.(4)			
			Date:	12/09/2020

**Wells Served By Facilities Above****AirsID**

API Number	API Number	AirsID
123-09231		

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**Facility ID: 241442 Type: WELL API Number: 123-09231 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: SI at time of inspection

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**Date of Last Brhd Test: 10/18/2020 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0Comment: appears to be plumbed to surface

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Monday 7/19/2021 at approximately 1010 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location: follow up inspection to Doc # 699302788 &amp; 699303558.</p> <p>O'Hara 2-9 at API #05-123-09231 in Weld County Colorado.</p> <p>While there, I observed wellsite and tank battery.</p> <p>During this inspection the following possible compliance issue was observed and is now delinquent:</p> <p>605.a.(4) Berms: Berm around Crud Tank is flattened out and needs repair. CA date 12-19-2020.</p> <p>See attached photos.</p> <p>Location is dry, weather is clear.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	revasr	07/19/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402752799	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5483063">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5483063</a>
699304095	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5483049">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5483049</a>