

Inspection Photos

API: 071-07915

Operator: WAPITI OPERATING LLC

Inspection Date: 7/22/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07915 | Date: 7/22/2021

Inspection Photos



Photo 1. Facing southwest along the main road in the canyon. Stormwater has washed across the road causing erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07915 | Date: 7/22/2021

Inspection Photos



Photo 2. The culvert outlet has been eroded and will need to be repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07915 | Date: 7/22/2021

Inspection Photos



Photo 3. Facing west along the road ascending the hill toward the location. Stormwater is not properly diverted toward the ditch shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07915 | Date: 7/22/2021

Inspection Photos



Photo 4. There is erosion along the side of the road which will need to be repaired and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07915 | Date: 7/22/2021

Inspection Photos



Photo 5. Facing back down the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07915 | Date: 7/22/2021

Inspection Photos



Photo 6. Facing toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07915 | Date: 7/22/2021

Inspection Photos



Photo 7. Facing toward the location. There are noxious weeds along the cut slope which need to be controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07915 | Date: 7/22/2021