

Inspection Photos

API: 071-08769

Operator: WAPITI OPERATING LLC

Inspection Date: 7/22/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08769 | Date: 7/22/2021

Inspection Photos



Photo 1. Facing southeast along the made road at the upper part of Lorencito Canyon. There is erosion along the road from recent storm event. Stormwater is bypassing the culvert.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08769 | Date: 7/22/2021

Inspection Photos



Photo 2. The culverts along the road are filled in with sediment causing stormwater to flow down the side of the road. Lat/Long:37.00499,-104.83742.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08769 | Date: 7/22/2021

Inspection Photos



Photo 3. Facing east along the access road near the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08769 | Date: 7/22/2021

Inspection Photos



Photo 4. Facing toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08769 | Date: 7/22/2021