

Inspection Photos

API: 071-09838

Operator: WAPITI OPERATING LLC

Inspection Date: 7/22/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09838 | Date: 7/22/2021

Inspection Photos



Photo 1. Facing southwest along the made road near the well site. Stormwater has washed across the road causing erosion. The culvert is filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09838 | Date: 7/22/2021

Inspection Photos



Photo 2. The culvert outlet will need to be repaired and stabilized with outlet protection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09838 | Date: 7/22/2021

Inspection Photos



Photo 3. Facing southwest toward the access road. There are noxious weeds that are wilted along the main road and at the location. (shown at red arrow)



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09838 | Date: 7/22/2021

Inspection Photos



Photo 4. There are noxious weeds that are wilted at the location. (shown at red arrow)



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09838 | Date: 7/22/2021

Inspection Photos



Photo 5. Facing west at the northeast side of the location. This area is not stabilized and there is an erosion channel that will need to be repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09838 | Date: 7/22/2021

Inspection Photos



Photo 6. Facing toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09838 | Date: 7/22/2021