

# Inspection Photos

7/21/2021

Operator: GUNNISON ENERGY LLC # 10515

Location ID: 324464

Gunnison County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: GUNNISON ENERGY LLC # 10515  
Location ID: 324464



**Photo 1:** Photo shows areas on the northwest end of the Location have not been reclaimed in accordance with Rule 1003.b.

Inspection Photos  
Operator Name: GUNNISON ENERGY LLC # 10515  
Location ID: 324464



**Photo 2:** Photo shows areas on the northwest end of the Location have not been reclaimed in accordance with Rule 1003.b.

Inspection Photos  
Operator Name: GUNNISON ENERGY LLC # 10515  
Location ID: 324464



July 21, 2021  
39.15630761N 107.47822369W

**Photo 3:** Photo taken from the west of the Location. Photo shows various unused equipment and/or debris now being stored off of the Location.



Inspection Photos  
Operator Name: GUNNISON ENERGY LLC # 10515  
Location ID: 324464



July 21, 2021  
39.15624904N 107.47823719W

**Photo 4:** Photo taken from the west of the Location. Photo shows various unused equipment and/or debris now being stored off of the Location. .

Inspection Photos  
Operator Name: GUNNISON ENERGY LLC # 10515  
Location ID: 324464



**Photo 5:** Photo taken from the west end of the Location. Photo shows a bucket containing unknown fluids; no safety labeling has been applied identifying contents; bucket has not been placed into secondary containment.

Inspection Photos

Operator Name: GUNNISON ENERGY LLC # 10515

Location ID: 324464



**Photo 6:** See comments under photo 5.

Inspection Photos  
Operator Name: GUNNISON ENERGY LLC # 10515  
Location ID: 324464



July 21, 2021  
39.15609392N 107.4775931W

**Photo 7:** Photo shows barrel containing antifreeze/coolant. Barrel requires secondary containment.

Inspection Photos  
Operator Name: GUNNISON ENERGY LLC # 10515  
Location ID: 324464



**Photo 8:** Previous inspections observed that good-housekeeping practices were not being performed; various unused equipment, trash debris, and equipment not necessary for production on this Location stored on the site. Photos 8-12 shows equipment/debris/etc.. has not been removed. Additionally, new pipe has been brought onto the location (Photos 10,11); this pipe is also not necessary for production on this Location, and has not been stored in a workman-like manner.

Inspection Photos  
Operator Name: GUNNISON ENERGY LLC # 10515  
Location ID: 324464



**Photo 9:** See comments under photo 8.

Inspection Photos  
Operator Name: GUNNISON ENERGY LLC # 10515  
Location ID: 324464



July 21, 2021  
39.15645363N 107.47781376W

**Photo 10:** See comments under photo 8.

Inspection Photos  
Operator Name: GUNNISON ENERGY LLC # 10515  
Location ID: 324464



July 21, 2021  
39.1563921N 107.47769229W

**Photo 11:** See comments under photo 8.

Inspection Photos  
Operator Name: GUNNISON ENERGY LLC # 10515  
Location ID: 324464



July 21, 2021  
39.15631911N 107.4773396W

**Photo 12:** See comments under photo 8.

Inspection Photos  
Operator Name: GUNNISON ENERGY LLC # 10515  
Location ID: 324464



**Photo 13:** Photo shows secondary containment around the tank battery remains inadequate.

Inspection Photos  
Operator Name: GUNNISON ENERGY LLC # 10515  
Location ID: 324464



July 21, 2021  
39.15626486N 107.4773913W

**Photo 14:** Photo shows secondary containment around the tank battery remains inadequate.

Inspection Photos  
Operator Name: GUNNISON ENERGY LLC # 10515  
Location ID: 324464



**Photo 15:** Photo taken from the southwest end of the Location, facing east. Photo shows noxious weed establishment on the Location.

Inspection Photos  
Operator Name: GUNNISON ENERGY LLC # 10515  
Location ID: 324464



**Photo 16:** Photo taken from the southwest end of the Location, facing south. Photo shows noxious weed establishment on the Location.