

Inspection Photos  
Operator: Simcoe  
API: 067-07088  
Date: 7/23/2021



Photo 1. View of the project area from the well pad entrance facing center.





Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing with western wheatgrass and smooth brome.





Photo 3. View of unstabilized cut-slope in the northern project area with erosional rilling and channeling up to 18 inches wide and deep. Long term stabilization measures are needed on exposed and eroding soils.





Photo 4. Another view of erosional rilling on the well pad cut-slope and sediment deposition at the base. Photo looking up-slope.





Photo 5. View the reference area comprised of ponderosa pine woodland with understory of gambel oak, serviceberry, western wheatgrass, and Oregon grape.