

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/07/2021

Submitted Date:

07/20/2021

Document Number:

690201819

**FIELD INSPECTION FORM**

Loc ID 308031 Inspector Name: COSTA, RYAN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10672  
Name of Operator: TIMBER CREEK OPERATING LLC  
Address: 6295 GREENWOOD PLAZA BLVD #100  
City: GREENWOOD State: CO Zip: 8111-

**Findings:**

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name   | Phone | Email                       | Comment |
|----------------|-------|-----------------------------|---------|
|                |       | efitzgerald@ogrisop.com     |         |
|                |       | timothy.thomsen@state.co.us |         |
| ATWATER BONNIE |       | batwater@ogrisop.com        |         |
|                |       | rmack@ogrisop.com           |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name       | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 260248      | WELL | SI     | 02/01/2021  | GW         | 071-07414 | APACHE CANYON 13-15 | RI          |

**General Comment:**

This is a follow up of the previous stormwater management inspection #690200853.  
The corrective action of the previous inspection has not been performed.  
See attached photos and additional details within this report.

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: There is vehicle rutting and erosion along the access road ascending the hill toward the location. Areas of erosion along the access road must be repaired and properly stabilized. Previous corrective action has not been performed.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 12/23/2020

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 402753431    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5483650">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5483650</a> |
| 690201820    | Inspection Photos    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5483631">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5483631</a> |