

Final Reclamation Inspection

July 16, 2021

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 320377

Inspection Document #: 697503082

Adams County, CO

NESW Section 5 T1S R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources



Photo 1. 2019 aerial imagery illustrates the well location and associated tank battery. There is a pre-existing main access road utilized for ditch water access right-of-way that is not the responsibility of the Operator to reclaim.

Inspection Photos
Location Name: DREYER #2
Location ID: 320377



Photo 2. Photo taken from the eastern location, facing East. Photo illustrates in response to the previous corrective action inspection from May 2018, reclamation has been performed at the location. Desirable perennial vegetation was observed but the location will remain in-process until it meet Rule 1004 vegetative requirements.

Inspection Photos
Location Name: DREYER #2
Location ID: 320377



Photo 3. Photo taken from the eastern location, facing West. See comments under Photo 2.

Inspection Photos
Location Name: DREYER #2
Location ID: 320377



Photo 4. Photo taken from the central location, facing Southwest. See comments under Photo 2.

Inspection Photos
Location Name: DREYER #2
Location ID: 320377



Photo 5. Photo taken from the central location, facing South. See comments under Photo 2.