



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type PUMP JACK

Comment: Panel

Corrective Action:

Date: \_\_\_\_\_

**Equipment:**

corrective date

Type: Deadman # & Marked # 4

Comment:

Corrective Action:

Date: \_\_\_\_\_

Type: Pump Jack # 1

Comment:

Corrective Action:

Date: \_\_\_\_\_

Type: Bradenhead # 1

Comment: Bradenhead valve is exposed at surface.

Corrective Action:

Date: \_\_\_\_\_

Type: Prime Mover # 1

Comment: Electric motor

Corrective Action:

Date: \_\_\_\_\_

Type: Flow Line # 1

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Flaring:**

Type

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Inspected Facilities**

Facility ID: 217045 Type: WELL API Number: 069-06232 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 10/24/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: WATER H2O

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697004181	Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5490339">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5490339</a>