

Inspection Photos

Location Name:TEP ROCKY MOUNTAIN LLC FEDERAL-66S96W /36NWNW

Location ID: 335189



Photo #4535 from entrance to location.



Photo #4536 from entrance to location.

Inspection Photos

Location Name:TEP ROCKY MOUNTAIN LLC FEDERAL-66S96W /36NWNW

Location ID: 335189



Photo #4537 Location lacks stabilization.



Photo #4538 Location lacks stabilization.

Inspection Photos

Location Name:TEP ROCKY MOUNTAIN LLC FEDERAL-66S96W /36NWNW

Location ID: 335189



Photo #4539 No form of tracking BMP located at entrance to location.



Photo #4540 Sediment and debris that over ran the access road.

Inspection Photos

Location Name:TEP ROCKY MOUNTAIN LLC FEDERAL-66S96W /36NWNW

Location ID: 335189



Photo #4541 Drainage that intersects access road.



Photo #4542 Drainage that intersects access road.

Inspection Photos

Location Name:TEP ROCKY MOUNTAIN LLC FEDERAL-66S96W /36NWNW

Location ID: 335189



Network time is not synchronize
Local:Jul 22, 2021 at 12:51:28 PM MD



Network time is not synchronize
Local:Jul 22, 2021 at 12:51:42 PM MD

Photo #4543 Sediment and debris that over ran the access road.

Photo #4544 Sediment choking off vegetation.

Inspection Photos

Location Name:TEP ROCKY MOUNTAIN LLC FEDERAL-66S96W /36NWNW

Location ID: 335189



Photo #4545 Sediment appears to have been bladed to the side of access road.



Photo #4546 Sediment appears to have been bladed to the side of access road.

Inspection Photos

Location Name:TEP ROCKY MOUNTAIN LLC FEDERAL-66S96W /36NWNW

Location ID: 335189



Photo #4549 Ditch that sediment was transported down and on to location #335096.




Photo #4550 Sediment and debris encroaching on production equipment.

Inspection Photos

Location Name:TEP ROCKY MOUNTAIN LLC FEDERAL-66S96W /36NWNW

Location ID: 335189



Sediment has been transported approximately 380 yards on to location #335096.