

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY /GM 34-14

Location ID: 334753



Photo #4581 from entrance to location.



Photo #4582 from entrance to location.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY /GM 34-14

Location ID: 334753



**Photo #4437 From inspection #699803405 conducted on 7/15/21.**



**Photo #4584 Sediment trap filled with sediment.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY /GM 34-14

Location ID: 334753



**Photo #4437** From inspection #699803405 conducted on 7/15/21.



**Photo #4583** drainage up stream of location.

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY /GM 34-14

Location ID: 334753



**Photo #4440** From inspection #699803405 conducted on 7/15/21.



**Photo #4586** Sediment encroaching on equipment.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY /GM 34-14

Location ID: 334753



**Photo #4585 Velocity checks have not been installed.**



**Photo #4588 Sediment has been bladed to the edge of ditch.**





## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY /GM 34-14

Location ID: 334753



**Photo #4441** From inspection #699803405 conducted on 7/15/21.



**Photo #4587** Ditch shows signs of subsidence.





## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY /GM 34-14

Location ID: 334753



**Photo #4443** From inspection #699803405 conducted on 7/15/21.



**Photo #4589** Sediment has been bladed into ditch.



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY /GM 34-14

Location ID: 334753



**Photo #4591 Sediment has been bladed into BMP.**



**Photo #4592 Sediment has been bladed into ditch.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY /GM 34-14

Location ID: 334753



**Photo #4445 From inspection #699803405 conducted on 7/15/21.**



**Photo #4593 Inlet of culvert under access road.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY /GM 34-14

Location ID: 334753



**Photo #4595 Culvert capacity reduced do to sediment and debris.**



**Photo #4594 Outlet of culvert.**





## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY /GM 34-14

Location ID: 334753



**Photo #4596 Waddles have not been maintained.**



**Photo #4600 Tracking BMP has not been implemented.**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY /GM 34-14

Location ID: 334753



Photo #4449 From inspection #699803405 conducted on 7/15/21.



Photo #4598 Sediment and debris that was transported on to HWY 6.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY /GM 34-14

Location ID: 334753



**Photo #4451** From inspection #699803405 conducted on 7/15/21.



**Photo #4602** Inlet of culver that runs under HWY 6.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources