

Inspection Photos

API: 071-08589

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 7/27/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08589 | Date: 7/27/2021

Inspection Photos



Photo 1. Facing southwest toward the access road which remains per approved variance.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08589 | Date: 7/27/2021

Inspection Photos



Photo 2. Facing southwest along the access road. The access road is stabilized with vegetation and gravel.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08589 | Date: 7/27/2021

Inspection Photos



Photo 3. Facing northwest along the access road. The access road is stabilized with vegetation and gravel.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08589 | Date: 7/27/2021

Inspection Photos



Photo 4. Facing southeast toward the location. The vegetation has established throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08589 | Date: 7/27/2021

Inspection Photos



Photo 5. Facing southeast along the fill slope which is stabilized with vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08589 | Date: 7/27/2021

Inspection Photos



Photo 6. There is rock rip/rap installed for stormwater drainage at the south side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08589 | Date: 7/27/2021

Inspection Photos



Photo 7. Facing northeast along the cut slope which is stabilized with vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08589 | Date: 7/27/2021

Inspection Photos



Photo 8. Facing southeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08589 | Date: 7/27/2021