

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/11/2021

Submitted Date:

07/22/2021

Document Number:

688800941**FIELD INSPECTION FORM**Loc ID 326325 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10663Name of Operator: ENDURING RESOURCES LLCAddress: 1050 17TH STREET SUITE 2500City: DENVER State: CO Zip: 80265**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**14 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Heil, John		john.heil@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Walter, Kyle		kwalter@enduringresources.com	All Inspections
Felix, Andrea		afelix@enduringresources.com	All inspections
Roy, Catherine		catherine.roy@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216235	WELL	PR	12/21/1991	GW	067-07841	W. ANIMAS-WHEELER 8-1	EI
288225	PIT	AC			-	WEST ANIMAS WHEELER 8-1	EI

**General Comment:**

On July 11, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Enduring Resources West Animas Wheeler #8-1. For the most recent field inspection report of this facility, please refer to document #693901646.

### Location

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Free standing location sign posted near PBV.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	PBV is labeled with capacity, contents, and NFPA placard.		
Corrective Action:		Date:	

Emergency Contact Number:		
Comment:	Posted on location sign.	
Corrective Action:		Date: _____

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	
Lube Oil		<= 1 bbl	
Comment:	Stained soil near generator.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.		Date: 08/23/2021

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Guard fencing present.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Prime Mover	# 1		
Comment:	Electric motor.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment:	Generator.	
Corrective Action:		Date:
Type: Vertical Heated Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Deadman # & Marked	# 2	
Comment:	Two markers observed during this inspection.	
Corrective Action:	Comply with Rule 603.j.	Date: 09/22/2021

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		37.216432,-107.872372
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	95 bbl.
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Wells Served By Facilities Above**

API Number
067-07841

**AirsID**

API Number	AirsID
------------	--------

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	216235	Type:	WELL	API Number:	067-07841	Status:	PR	Insp. Status:	EI
Facility ID:	288225	Type:	PIT	API Number:	-	Status:	AC	Insp. Status:	EI

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	In Process	Compaction	Pass	Material Handling And Spill Prevention	Pass	Drip pot on load out line.
Compaction	In Process	Gravel	Pass	Material Handling And Spill Prevention	Pass	Secondary containment for lube oil container.
Waddles	In Process	Culverts	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On July 11, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Enduring Resources West Animas Wheeler #8-1. For the most recent field inspection report of this facility, please refer to document #693901646. During this inspection staining was observed near the generator. Erosion along the eastern edge of the location needs to be addressed.	hughesjo	07/22/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402757230	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5486715">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5486715</a>
688800942	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5486708">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5486708</a>