

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/16/2021

Submitted Date:

07/21/2021

Document Number:

701101743

FIELD INSPECTION FORMLoc ID 314775 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10027

Name of Operator: C & J FIELD SERVICES

Address: 3650 COUNTY RD #2

City: RANGELY State: CO Zip: 81648

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

7 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Thompson, Bud		BLThomps@BLM.gov	
, C&J Field Services		candjfield@centurytel.net	
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Engineering		dnr_cogccengineering@state.co.us	All engineering

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229554	WELL	SI	04/01/2021	OW	103-07211	GOV'T 1	PR

General Comment:**COGCC Routine Inspection Report Summary**

During this inspection the following compliance issues were observed:

- Surface casing open to atmosphere.
- No braden accessible on well.
- Weeds on location.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. Location is with a Rule 1202.d Mule deer severe winter range area and a Rule 1202.d Mule deer winter concentration area.

LocationOverall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911	
Corrective Action:		Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds on location.		
Corrective Action:	Comply with Rule 606	Date:	08/06/2021

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type			
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Bradenhead	# 0		corrective date
Comment:	No braden accessible on well. Surface casing open to atmosphere.		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2) Contact COGCC Engineering staff		Date: 08/06/2021
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:

Venting:

Yes/No		
--------	--	--

Comment:	Surface casing open to atmosphere. A FLIR Camera inspection will be planned at a later date.		
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 229554 Type: WELL API Number: 103-07211 Status: SI Insp. Status: PR**Producing Well**Comment: [Production valve open on prodcuton line at well.](#)

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402757530	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5486970
701101747	Inspection 701101743 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5486966