

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/20/2021

Submitted Date:

07/29/2021

Document Number:

689806099

FIELD INSPECTION FORM

Loc ID 313046 Inspector Name: Waldron, Emily On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 3975
Name of Operator: ARGALI EXPLORATION COMPANY
Address: PO BOX 416
City: RANGELY State: CO Zip: 81648

Findings:

- 8 Number of Comments
- 7 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|-------|------------------------------------|---------|
| General, Contact | | argaliexplorationcompany@gmail.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 223451 | WELL | SI | 01/01/2020 | GW | 081-06817 | FEDERAL 4-35 | SI |

General Comment:

Routine FIU inspection. Form 9 to transfer from Mustang to Argali approved 10/6/2020 document number 402424253. Compliance issues observed:
signs inaccurate
no bradenhead access apparent
weeds
stormwater on access road

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|---|-------|------------|
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Tank label incomplete. | | |
| Corrective Action: | Install sign to comply with Rule 605.h. | Date: | 08/30/2021 |
| Type | WELLHEAD | | |
| Comment: | Wellhead sign inaccurate. | | |
| Corrective Action: | Install sign to comply with Rule 605.d. | Date: | 08/30/2021 |
| Type | BATTERY | | |
| Comment: | Battery sign inaccurate/incomplete. | | |
| Corrective Action: | Install sign to comply with Rule 605.e. | Date: | 08/30/2021 |

Emergency Contact Number:

| | | | |
|--------------------|--|-------|------------|
| Comment: | No emergency contact information for current operator on location. | | |
| Corrective Action: | Install sign to comply with Rule 605. | Date: | 08/30/2021 |

Good Housekeeping:

| | | | |
|--------------------|--|-------|------------|
| Type | WEEDS | | |
| Comment: | Dried and living annual weeds on location. | | |
| Corrective Action: | Comply with Rule 606. | Date: | 08/05/2021 |

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

| Type: | | # | | corrective date |
|-----------------------------|---|-----|-------|-----------------|
| Bradenhead | | | | |
| Comment: | Bradenhead inaccessible or not visible. | | | |
| Corrective Action: | Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2) | | Date: | 08/09/2021 |
| Horizontal Heated Separator | | # 1 | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |
| Bird Protectors | | # | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |

| Tanks and Berms: | | | | | | |
|-------------------------|----------|---------------------|---------------------|-------------|--------|--|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| PRODUCED WATER | 1 | 200 BBLs | STEEL AST | | , | |
| Comment: | | | | | | |
| Corrective Action: | | | | | Date: | |
| Paint | | | | | | |
| Condition | Adequate | | | | | |
| Other (Content) | | | | | | |
| Other (Capacity) | | | | | | |
| Other (Type) | | | | | | |
| Berms | | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | | |
| Earth | Adequate | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | Date: | |
| Venting: | | | | | | |
| Yes/No | NO | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | Date: | |
| Flaring: | | | | | | |
| Type | | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | Date: | |

Inspected Facilities

Facility ID: 223451 Type: WELL API Number: 081-06817 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: [Sediment migration apparent on access road.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.\(2\)C](#)

Date: 08/05/2021

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 689806100 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5492274 |