

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

07/29/2021

Submitted Date:

07/29/2021

Document Number:

690008064**FIELD INSPECTION FORM**
 Loc ID 336588 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
, Oxy		COGCCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
250657	WELL	SI	06/01/2020	GW	123-18460	UPRC 9-12J5	SI
297705	WELL	SI	06/01/2020	GW	123-28045	REI H 9-33D	SI
300665	WELL	SI	06/01/2020	OW	123-29814	REI H 9-32D	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Location number: 328169				
Corrective Action:				Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:			Date:	

AirsID

Inspected Facilities

Facility ID: 250657 Type: WELL API Number: 123-18460 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: SI and locked at wellhead connection with flow line.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 12/10/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: --

Comment: Plumbed to surface.

Corrective Action: _____ Date: _____

Facility ID: 297705 Type: WELL API Number: 123-28045 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: Shut in at wellhead connection with flow line.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 01/16/2020 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 11 Fluid Type: _____

End Surf Csg Pressure: 1

Comment: Plumbed to surface.

Corrective Action: _____ Date: _____

Facility ID: 300665 Type: WELL API Number: 123-29814 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: SI at flow line connection with flow line.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 01/16/2020 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Plumbed to surface.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
Routine wellhead inspection.	carlilec	07/29/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690008065	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5492530